


5501F3 Valencia Two Tier Fountain 3 pc.





Winter ice build-up can damage concrete statuary. Follow these tips to reduce winter weathering to your fountain:

- * Disconnect power to pump
- * Remove plugs/stopper in all fountain bowls to open drains and let all moisture out. Keep drains open throughout the winter.
- * Place an absorbant material like burlap, blankets, etc. inside bowls and cover everything with a Henri fountain cover.
- * Do not allow snow or ice to build up on or against the concrete. Remove snow before it turns to ice. Do not use salt of chemical ice removers as they may damage concrete.







Hold tubing exiting above the 6501 with a stopper. Press in firmly. Attach larger adapter to the end of the tube, barb side into tube.

